Induction Motors



Introduction

Three-phase induction motors are the most common and frequently encountered machines in industry

- simple design, rugged, low-price, easy maintenance
- wide range of power ratings: fractional horsepower to 10 MW
- run essentially as constant speed from no-load to full load
- Its speed depends on the frequency of the power source
- not easy to have variable speed control
- Speed is determined by the supply frequency
- To vary its speed need a variable frequency supply

> An induction motor has two main parts

- a stationary stator
 - consisting of a steel frame that supports a hollow, cylindrical core
 - core, constructed from stacked laminations (why?), having a number of evenly spaced slots, providing the space for the stator winding



- a revolving rotor
 - composed of punched laminations, stacked to create a series of rotor slots, providing space for the rotor winding
 - one of two types of rotor windings
 - conventional 3-phase windings made of insulated wire (wound-rotor) » similar to the winding on the stator
 - aluminum bus bars shorted together at the ends by two aluminum rings, forming a squirrel-cage shaped circuit (squirrel-cage)
- Two basic design types depending on the rotor design
 - squirrel-cage: conducting bars laid into slots and shorted at both ends by shorting rings.
 - wound-rotor: complete set of three-phase windings exactly as the stator. Usually Y-connected, the ends of the three rotor wires are connected to 3 slip rings on the rotor shaft. In this way, the rotor circuit is accessible.



Squirrel cage rotor



Slip Ring Rotor

- •The rotor contains windings similar to stator.
- •The connections from rotor are brought out using slip rings that are rotating with the rotor and carbon brushes that are static.





Cutaway in a typical woundrotor IM. Notice the brushes and the slip rings

Rotating Magnetic Field

- Balanced three phase windings, i.e. mechanically displaced 120 degrees from each other, fed by balanced three phase source
- A rotating magnetic field with constant magnitude is produced, rotating with a speed

$$n_{sync} = \frac{120f_e}{P}$$
 rpm

Where f_e is the supply frequency and

P is the no. of poles and n_{sync} is called the synchronous speed in *rpm* (revolutions per minute)



Synchronous speed

Р	50 Hz	60 Hz
2	3000	3600
4	1500	1800
6	1000	1200
8	750	900
10	600	720
12	500	600





Principle of operation

- This rotating magnetic field cuts the rotor windings and produces an induced voltage in the rotor windings
- Due to the fact that the rotor windings are short circuited, for both squirrel cage and wound-rotor, and induced current flows in the rotor windings
- > The rotor current produces another magnetic field
- A torque is produced as a result of the interaction of those two magnetic fields

$$\tau_{ind} = kB_R \times B_s$$

Where τ_{ind} is the induced torque and B_R and B_S are the magnetic flux densities of the rotor and the stator respectively

Induction motor speed

- \succ At what speed will the IM run?
 - Can the IM run at the synchronous speed, why?
 - If rotor runs at the synchronous speed, which is the same speed of the rotating magnetic field, then the rotor will appear stationary to the rotating magnetic field and the rotating magnetic field will not cut the rotor. So, no induced current will flow in the rotor and no rotor magnetic flux will be produced so no torque is generated and the rotor speed will fall below the synchronous speed
 - When the speed falls, the rotating magnetic field will cut the rotor windings and a torque is produced

Induction motor speed

- So, the IM will always run at a speed lower than the synchronous speed
- The difference between the motor speed and the synchronous speed is called the *Slip*

$$n_{slip} = n_{sync} - n_m$$

Where n_{slip} = slip speed n_{sync} = speed of the magnetic field n_m = mechanical shaft speed of the motor

The Slip

$$s = \frac{n_{sync} - n_m}{n_{sync}}$$

Where *s* is the *slip*

Notice that : if the rotor runs at synchronous speed

s = 0

if the rotor is stationary

s = 1

Slip may be expressed as a percentage by multiplying the above eq. by 100, notice that the slip is a ratio and doesn't have units

Induction Motors and Transformers

- Both IM and transformer works on the principle of induced voltage
 - Transformer: voltage applied to the primary windings produce an induced voltage in the secondary windings
 - Induction motor: voltage applied to the stator windings produce an induced voltage in the rotor windings
 - The difference is that, in the case of the induction motor, the secondary windings can move
 - Due to the rotation of the rotor (the secondary winding of the IM), the induced voltage in it does not have the same frequency of the stator (the primary) voltage

Frequency

The frequency of the voltage induced in the rotor is given by

$$f_r = \frac{P \times n}{120}$$

Where f_r = the rotor frequency (Hz)

P = number of stator poles

n = slip speed (rpm)

$$f_r = \frac{P \times (n_s - n_m)}{120}$$
$$= \frac{P \times sn_s}{120} = sf_e$$

Frequency

> What would be the frequency of the rotor's induced voltage at any speed n_m ?

$$f_r = s f_e$$

- > When the rotor is blocked (s=1), the frequency of the induced voltage is equal to the supply frequency
- > On the other hand, if the rotor runs at synchronous speed (s = 0), the frequency will be zero

(2) Effect of Slip on rober Induced Emf :--
When the roter is glabionary or shard still i.e.,
$$Slip = \frac{N_{S}-N}{N_{S}} = \frac{N_{S}-N}{N_{S}}$$

Since $N = 0$ when retry is glabionary $\implies S = \frac{N_{S}-N}{N_{S}}$
 $\implies S = \frac{N_{S}-0}{N_{S}}$
 $\implies S = 1$, the enf Induced in the roter is maximum.
 $\implies S = 1$, the enf Induced in the roter is maximum.
 $\implies A_{S}$ roter jains speed, the roter is maximum.
 $\implies A_{S}$ roter Jains speed, the roter is the roter, proportionally.
 $= \frac{A_{S}}{S}$ roter Induced $enf/phase at shandstill,$
 $E_{Z} \ll N_{S} = \frac{N_{S}-N}{N_{S}} = \frac{N_{S}}{N_{S}}$
 $= \frac{N_{S}-N}{E_{Z}} = \frac{N_{S}-N}{N_{S}} = S$
 $\implies E_{Z'} = \frac{N_{S}-N}{N_{S}} = S$
 $\implies E_{Z'} = \frac{N_{S}-N}{N_{S}} = S$
 $\implies E_{Z'} = S \cdot E_{Z}$
 a^{*} Roter Induced emf under summing Condition will be glip times

the volos Induced Emf at stand ski

Effect of slip on Rotos Reachance, Resistance and Impedence V = Florent and an OBA branks In sendal Robir Reachance : Let L2 = Inductance of rotor per phase At standfill: fr = f, hence notive Reactance/phase of standsfill, $X_2 = 2\pi f_{\delta} h_2$ $\left[\begin{array}{c} X_2 = 2 \pi f L_2 \end{array} \right].$ Under Running Condition : i.e., at slip 's', fr = sf hence Relier reactance/phase under orunning Condition, $X_{2s} = 2\pi f_s h_2$ = 27 (Sf). L2 = 5 (2nfl2) $X_{2r} = S X_2$ o's Rotor Reachance under Running Condition will be slip times the rolos reactance at stand still. Rotor Resistance: Let R2 = stand still order resistance /phase. Rotor resistance is Independent of frequency and hence ortor resistance servine same as 'R2' --- /phase at shorthill and in occurning Condition

Rolor Ampedence: Rotor Impedance/phase at Stand & All is $Z_2 = R_2 + j x_2 = \sqrt{R_2^2 + x_2^2}$ Retor Impedance phase at ounning andition is Tax = R2+ j(SX2) = TR2+ (SX2) Effect of slip on Rotor Current and power factor :-At stand \$fill: Let I2 = standstill votor current/phase. Cosep_= power factor of rotor at stand still. then equivalent circuit of ortor at stand ettil is shown in fig () $E_{2} \sim \frac{1}{2} = \sqrt{\frac{1}{R_{1}^{1} + X_{2}^{2}}}$ $Z = R_{2} + j X_{2}$ $IZI = \sqrt{\frac{1}{R_{1}^{1} + X_{2}^{2}}}$ figO $C_{05}\phi_{2} = \frac{R_{2}}{Z_{2}} = \frac{R_{2}}{\sqrt{R_{2}^{2} + \chi_{2}^{2}}}$ where $E_2 = stand still robor Induced Emg[phase.$ At Running Condition : Equivalent circuit under orunning Condition is shown in fig () RL X12= SX2 $Z = R_2 + j(S \times 2)$ $|Z| = \sqrt{R_1^2 + (SX_2)^2}$

. .. Roline Current / phase Under manning Condition . $\frac{\hat{1}_{2Y}}{Z_{2Y}} = \frac{E_{2Y}}{Z_{2Y}} = \frac{S \cdot E_2}{\sqrt{R_2^2 + (SX_2)^2}} \qquad (:: E_{2Y} = SE_2)$ $C_{05}\phi_{2v} = \frac{R_2}{Z_{2v}} = \frac{R_2}{-\sqrt{R^2 + (5x)^2}}$ losque Equation of an Induction Molos g-The Torque, T of an Induction motion is proportional to the product of statos flux por pole (4), rotos current (I2) and the P.f of solos. The Tosque of an Induction motor is due to the Interaction of rotor and station fields Thus, T & \$ In Cost Since voter Induced emp/phase, E20 is propositional to state flux, i.e., Eze x ¢ ·· TX Ex In Cost2 $\begin{array}{c} \textbf{S}.\\ \textbf{E}\\ \textbf{C}\\ \textbf{C}\\ \textbf{C}\\ \textbf{C}\\ \textbf{C}\\ \textbf{S}.\\ \textbf{C}\\ \textbf{C$ $\implies T \ll \frac{S E_2^2 \cdot R_2}{R_1^2 + (SX)^2}$

$$\begin{aligned} \frac{1}{ds} \begin{bmatrix} k \cdot \frac{s}{s} \frac{s}{k_{+}} \frac{k_{+}}{(s \times s)^{2}} \end{bmatrix} = 0 \\ k \cdot \frac{1}{ds} \begin{bmatrix} \frac{s}{k_{+}} \frac{s}{(s \times s)^{2}} \end{bmatrix} = 0 & -3 \\ k \cdot \frac{1}{ds} \begin{bmatrix} \frac{s}{k_{+}} \frac{s}{(s \times s)^{2}} \end{bmatrix} = 0 & -3 \\ equation (S) is is the form of $\frac{1}{k_{+}} (s \times s)^{2} \end{bmatrix} = 0 & -3 \\ \Rightarrow & k \cdot \begin{bmatrix} k_{+} (s \times s)^{2} \end{bmatrix} (k_{+}^{2} k_{+}) - (s \times s^{2} k_{+}) (0 + (2 \times x)^{2} \times s) \\ \Rightarrow & \begin{pmatrix} k \cdot \frac{1}{k_{+}} (s \times s)^{2} \end{bmatrix} (k_{+}^{2} k_{+}) - (s \times s^{2} k_{+}) (0 + (2 \times x)^{2} \times s) \\ (R_{+}^{2} + (s \times s)^{2})^{2} \end{bmatrix} = 0 \\ \begin{pmatrix} R_{+}^{2} + (s \times s)^{2} \end{bmatrix} (k_{+}^{2} k_{+}) - (s \times s^{2} k_{+}) (s \times x^{2}) = 0 \\ (R_{+}^{2} + (s \times s)^{2}) \end{bmatrix} (k_{+}^{2} + (s \times s)^{2} = 2 \cdot s^{2} \times s^{2} \\ R_{+}^{2} + (s \times s)^{2} \end{bmatrix} (k_{+}^{2} + (s \times s)^{2}) = 2 \cdot s^{2} \times s^{2} \\ R_{+}^{2} + (s \times s)^{2} = 2 \cdot s^{2} \times s^{2}$$$

The condition for maximum trapue at sharing Ga to obtained by
Rudsthilding S=1 in equation (1), the get

$$\Rightarrow [R_3 = X_3]$$

 \Rightarrow Starking trappes its maximum, when roles substance to equal
to rate succentee at stand SHI.
Expression for the Maximum Torque 8-
bet know, $T = k \cdot \frac{S \cdot E_3^2 \cdot R_3}{R_2^2 + (SX_3)^2}$
The maximum trappe Can be obtained by Substituting $R_3 = SX_3$
in trappe equation (\cdot : $R_3 + SX_4$ is the Condition for more trappe)
 $\Rightarrow T_{max} = \frac{K \cdot SE_3^2 (SX_3)}{2 (SX_3)^2} = \frac{K \cdot SE_3^2}{2S X_4}$
 \Rightarrow From the Suppression of Trave, it can be obtained that success the super-
 $R_3 = \frac{K \cdot SE_3^2 (SX_3)}{2 (SX_3)^2} = \frac{K \cdot SE_3^2}{2S X_4}$

To cause showed by plotting troque against step is caused
The curve obtained by plotting troque against step is caused
Toque - step characteristics of Induction mater.
We know, toque
$$T = K$$
. $\frac{SE^2 \cdot R_1}{R_1^2 + (SR_2)^2}$
 \Rightarrow if supply values is omit then E. is doe onst.
 \Rightarrow the concentrate value of troppe of different values of step
in the sample form \circ to 1 .
(i) then step $S = 0$, $N = N_S$ and hence troppe, $T = 0$. Motor
cannot sum at superhomeness speed.
(ii) when step S' is very low i.e., the speed is very rease to
synchronous speed, then the term $(SR_2)^2$ is very 2 must
and can be neglected in comparision with R_1^2 .
 $\therefore T \ll \frac{S}{R_2} = (SR)$
 $[T \ll S = 1]$ if R_2 is caushed
there for low values of Step, the borque step curve is
a straight line.
(iii) when step Super discusses i.e., the speed decreases (with showed built
the torque discusses and becomes maximum taken
 $S = Sm = \frac{R_2}{R_2}$.

maximum troque is called as pull out or break down torque.

(IV) When Ship is further Increases beyond S = Sm, then the term R2 is very small as compared to (SX) and may be reglected. $\cdot \cdot T \times \frac{S \cdot R_{+}}{(S \times)^{2}}$ (or) TX - if R2 & X2 are constants. Alerce for higher values of slip, the torque slip curve is a sectorquer hyperbole. (V) If slip, S=1, then motor is stationary hence corresponding torque is nothing but starting torque. i.e., T = Tst when s=1. 5=1 5=0 S=Sm (N=NS) (N=0) speed Torque ship & torque speed characteristics.