


# **PART –A IMPORTANT QUESTIONS**

1) Give the conventional representation of a cylindrical helical tension spring, cylindrical helical compression spring, semi-elliptic leaf spring, internal threading, external threading, spur gear, bearings and diamond knurling.



2) What are the different standard sizes of drawing sheets? Give their designations and sizes.

- There are five standard sizes for drawing sheets, specified by Bureau of Indian Standards (BIS) SP: 46-1988, as given below.
- Drawing sheets may be used with their longer sides positioned horizontally.

Designation	Dimensions (mm)
A0	841 X 1189
A1	594 X 841
A2	420 X 594
A3	297 X 420
A4	210 X 297

### 3) What are the Elements of production drawing?

- Following are the basic elements of a production drawing.
- Format of drawing sheet,
- Size and shape of the component,
- Projection method,
- Material specification and shape such as castings, forgings, plates, rounds, etc.,
- Indication of surface roughness and other heat treatments, if any,
- Limits, fits and tolerances of size, form, and position,
- Production method,
- Process sheet,
- Specification of standard components,
- Conventions used to represent certain machine components,
- Inspection and testing methods.

### 4) What do you mean by production Drawing?


#### production Drawing

A component or part drawing is termed as a production drawing. It is an authorized document to produce the component in the shop floor.


### 5) Draw and describe about industrial oriented title block?

A production drawing may include the following additional information, located either in the drawing sheet or in the title block:

1. Job order number,
2. Surface treatment, roughness, etc.,
3. Key to machining and other symbols,
4. A general note on tolerance on dimensions, not individually tolerance.
5. Reference to tools, gauges, jigs and fixtures,
6. Parts list, and
7. Alternations and revisions.



6) Write down the meaning of the weld symbols as shown in below.



- (A) Double – U butt weld
- (B) Double – bevel butt weld (K weld)
- (C) Double – V butt weld (X weld)
- (D) Flat- Single V-butt weld
- (E) concave fillet weld
- (F) Single V-butt weld

7) Draw the symbol for fixed displacement hydraulic pump Bi-directional



8) Define interchangeability.

The term interchangeability refers to the parts which go into the assembly at random, from a lot.

Eg:- A nut and a bolt of a particular size may be assembled by selecting at random from the lots. In this any nut should be able to get assembled with any bolt.

9) Define tolerance, types with examples allowance.

**TOLERANCE :-**

It is the difference between the maximum and minimum permissible limits of the given size.

Tolerance = upper limit – lower limit.

If the variation is provided on one side of the basic size it is termed as unilateral tolerance. Similarly, if the variation is provided on both sides of the basic size, it is known as bilateral tolerance.

**ALLOWANCE :-**

It is the internal difference between the hole and shaft dimensions after their assembly is called allowance.

10) What is fit and what are the various types of fits?

**FIT:-**It is the degree of looseness or tightness between two mating parts to perform a definite function.

**TYPES OF FITS:-**

There are three types of fits

- 1) Clearance fit
- 2) Interference Fit
- 3) Transition Fit

**11) what are the various types of fits?explain briefly?**

**1)Clearance fit**


This fit arises when the diameter of shaft is smaller than hole. The minimum diameter of hole is greater than the largest permissible diameter of the shaft. The value of clearance fit is always positive.

**2)Interference Fit**

In this type of fit the minimum permissible diameter of the shaft is larger than the maximum allowable diameter of the hole. As the diameter of shaft is larger than the diameter of hole, the hole and shaft are intended to be attached permanently.

**3)Transition Fit**

This fit may result in either interference or a clearance, depending on the actual values of the tolerance of individual parts.



**12) What is the difference between hole basis system and shaft basis system.**

**HOLE BASIS SYSTEM**

In this system Hole is kept constant, Shaft size is varied to get different fits.

**SHAFT BASIS SYSTEM**

In this system Shaft is kept constant, Hole size is varied to get different fits.

**13) Expand the following abbreviations**

- |                                 |                 |                        |
|---------------------------------|-----------------|------------------------|
| a) HTS (HIGH TENSILE STEEL)     | b)CHD (CHECKED) | c)CrS (CHROMIUM STEEL) |
| d) TCS (TUNGSTEN CARBIDE STEEL) | e)CRS (centres) | f)CSK (COUNTER SUNK)   |
| g) BRG (BEARING)                |                 |                        |

Designation	Welding process	Designation	Welding process
CAW	Carbon arc welding	IB	Induction brazing
CW	Cold welding	IRB	Infra red brazing
DB	Dip brazing	OAW	Oxy-acetylene welding
DFW	Diffusion welding	OHW	Oxy-hydrogen welding
EBW	Electron beam welding	PGW	Pressure gas welding
ESW	Electro slag welding	RB	Resistance brazing
EXW	Explosion welding	RPW	Projection welding
FB	Furnace brazing	RSEW	Resistance seam welding
FOW	Forge welding	RSW	Resistance spot welding
FRW	Friction welding	PW	Resistance welding
FW	Flash welding	SAW	Submerged arc welding
GMAW	Gas metal arc welding	TB	Torch brazing
GTAW	Gas tungsten arc welding	UW	Upset welding

14) For the following assemblies, with a basic size of 50mm calculate Hole tolerance , shaft tolerance, minimum and maximum allowance and type of fit.

a)H7/g6

b)H8/k6

For the following assemblies, with a basic size of 50mm calculate hole tolerance, shaft tolerance, minimum and maximum allowance and type of fit.

- a) H7/g6      b) H8/k6

Sol Given Data:-


Basic size = 50mm.

a) H7/g6

From tolerance tables at  $\phi 50$ mm the limits for shaft is  $50^{-0.025}$  and for hole the limits are  $50^{+0.025}$

$$\text{Hole } 50^{+0.025} = 50^{0.025/0.000}$$

$$\text{shaft } 50^{-0.025} = 50^{0.009/0.025}$$



we know

$$\boxed{\text{Tolerance} = \text{Upper limit} - \text{Lower limit}}$$

$$\begin{aligned} \text{i) Hole tolerance} &= \text{Upper limit of hole} - \text{Lower limit of hole} \\ &= 50.025 - 50.000 \\ &= 0.025 \text{ mm.} \end{aligned}$$

$$\begin{aligned} \text{ii) shaft tolerance} &= \text{Upper limit of shaft} - \text{Lower limit of shaft} \\ &= 49.991 - 49.975 \\ &= 0.016 \text{ mm.} \end{aligned}$$

$$\begin{aligned}
 \text{iii) minimum allowance} &= \text{Lower Limit of hole} - \text{Upper Limit of shaft} \\
 &= 50.000 - 49.991 \\
 &= 0.009 \text{ mm}
 \end{aligned}$$

$$\begin{aligned}
 \text{iv) maximum allowance} &= \text{Upper Limit of hole} - \text{Lower Limit of shaft} \\
 &= 50.025 - 49.975 \\
 &= 0.05 \text{ mm}
 \end{aligned}$$

v) Type of fit :-

From the above diagram it is clear that the given fit is clearance fit.

b) H8/k6

From the tolerance tables the upper and lower limit for basic size 50mm at H8 & k6 are

Hole	$50^{+0}$	=	$50^{0.000}$
Shaft	$50^{+0.018}$	=	$50^{+0.002}$

i) Hole tolerance =  $50.039 - 50.000 = 0.039 \text{ mm}$


ii) Shaft tolerance =  $50.018 - 50.002 = 0.016 \text{ mm}$

iii) minimum allowance =  $50.000 - 50.018 = -0.018 \text{ mm}$

iv) maximum allowance =  $50.039 - 50.002 = 0.037 \text{ mm}$

v) Type of fit :-

From the figure (b) it is clear that the given fit is TRANSITION FIT.




(b)




15) Find the limits of the following shafts and holes 20h6,60p7,20H6 and 75H11.

16) State the type of fit obtained for hole diameter 33.00mm & 33.24mm and shaft diameter 33.11mm & 34.05mm.

17) Draw the symbol for surface roughness and abbreviate a,b,c,d,e and f.



18) What is the meaning of below mentioned symbols.



(A)



(B)

(A) Basic symbol used when the removal of material by machining process is needed.







(B) Basic symbol used when the removal of material is not allowed.

19) What are the surface finish values for Lapping, Honning, burnishing, Grinding, filing, turning and milling, Reaming, Hobbing, Drilling and sand casting in microns.

Lapping	-	0.012 to 0.16
Honning	-	0.025 to 0.4
Burnishing	-	0.04 to 0.8
Grinding	-	0.063 to 5
Filing	-	0.25 to 25
Turning and milling	-	0.32 to 25
Reaming	-	0.4 to 3.2
hobbing	-	0.4 to 3.2
Drilling	-	1.6 to 20
sand casting	-	5 to 50












20) Specify all the direction of lay and their meaning which are represented in surface roughness.

=	Parallel to the plane of projection of the view in which the symbol is used	
⊥	Perpendicular to the plane of projection of the view in which the symbol is used	
X	Crossed in two slant directions relative to the plane of projection of the view in which the symbol is used	
M	Multi-directional	
C	Approximately circular relative to the centre of the surface to which the symbol is applied	
R	Approximately radial relative to the centre of the surface to which the symbol is applied	

21) What are the symbols for the following

Cylindricity, profile of any line, profile of any surface, parallelism, angularity, position, concentricity, symmetry.

Cylindricity	
Profile of any line	
Profile of any surface	
Parallelism	
Perpendicularity (squareness)	
Angularity	
Position	
Concentricity and coaxiality	
Symmetry	

22) Give the description for the following notes on a drawing.

**THD RELIEF, Ø30 WIDE 4.**


**6 HOLES, EQUI-SP DIA 17 C BORE FOR M16 SOCKET HD CAP SCR.**

**DIA 25 DEEP 25**


**DIA 10 CSK DIA 15**

NOTE	MEANING
THD RELIEF, Ø30 WIDE 4.	Cut a relief for thread with a diameter of 30mm and width 4mm
6 HOLES, EQUI-SP DIA 17 C BORE FOR M16 SOCKET HD CAP SCR.	Drill a through hole of dia 17 and counterbore to insert a socket headed cap screw of M16. Six holes are to be made equi-spaced on the circle.
DIA 25 DEEP 25	Drill a hole of diameter 25mm, to a depth of 25mm
DIA 10 CSK DIA 15	Drill a through hole of diameter 10mm and countersink to get 15mm on top.

23) Mention the standard representation for rivet.



24) Explain all orientation symbols in geometric dimensioning tolerance with example.



25) Indicate the roughness symbols and roughness values for roughness N1, N2, N5 and N9.

Roughness grades	Roughness values ( $R_a$ ) in microns	Roughness symbol
N1	0.025	
N2	0.05	
N5	0.4	
N9	6.3	
N10	12.5	

**26) Explain the position of the symbol with regard to the reference line**




Single V – Butt weld at arrow side.

**27) What is the difference between caulking and fullering.**

<b>Caulking</b>	<b>Fullering</b>
It is used to obtain leak proof joints.	It is also used to obtain leak proof joints.
It is carried out by using a narrow blunt tool called caulking tool.	It is carried out by using fullering tool.
The thickness of the tool is about 5mm.	The thickness of the tool is equal to the thickness of the plates.
Surface finish obtained is less.	Surface finish obtained is more.
More risk of distortion of plates.	Less risk of distortion of the plates.


## **PART -B IMPORTANT QUESTIONS**

- Q1). Study the given assembly drawing of the Stuffing Box as shown in below figure.**
- a) Draw the component drawings.**
  - b) Apply suitable tolerances and fits.**
  - c) Apply suitable geometrical tolerances to components.**
  - d) Show the surface roughness symbols.**
  - e) Prepare the process sheet for Gland.**



**Parts List**

Part No.	Name	Matl.	Qty.
1	Gland	Brass	1
2	Nut, M12	MS	2
3	Stud	MS	2
4	Body	CI	1
5	Bush	Brass	1
6	Shaft	MS	1



**Fig 9.12 Stuffing box**

1ANS)




Fig. 9.13 Details of stuffing box




Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	—	Check the dimensions of component	Vernier calipers			
10	Lathe	Fix the component in chuck through portion $\phi 50 \times 9$ mm and perform facing on the end and oval section of gland.	Facing tool			
15	Lathe	Turn the component $\phi 42 \times 45$ mm	Turning tool			
20	Lathe	Drill $\phi 20$ mm hole	Drill bit			
25	Lathe	Bore the hole upto $\phi 24$ mm	Boring tool			
30	Lathe	Chamfer the hole end	Turning tool			
35	Lathe	Reverse the component				
40	Lathe	Face the end and flange surface	Facing tool			
45	Lathe	Turn the component $\phi 50$ mm	Turning tool			
50	Lathe	Bore R12	Boring tool			
55	Drilling machine	Drill two holes of $\phi 13$ mm	Drill jig			
60	—	Inspect and verify the component size	Outside micrometer, vernier caliper, etc.			



**Q2). Study the given assembly drawing of the Eccentric as shown in below figure.**


- a) Draw the component drawings.**
- b) Apply suitable tolerances and fits.**
- c) Apply suitable geometrical tolerances to components.**
- d) Show the surface roughness symbols.**
- e) Prepare the process sheet for Straps.**



**Parts List**

Part No.	Qty.	Name	Matl.
1	1	Strap	CI
2	1	Sheave	CI
3	2	Shim	Brass
4	1	Strap	CI
5	2	Bolt with nuts	MS

2ANS)



**Process Sheet**

Part Name : Straps

Part Number : 1 and 4

Cycle Time :

Material : Cast iron

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the size of castings	Vernier calipers			
10	Milling	Slab-mill the faces of straps	Slab mill cutter			
15	Milling	Spot facing to provide seats for bolt heads	End mill cutter $\phi$ 40 mm			
20	Drilling	Drill holes of $\phi$ 16 mm	Drill $\phi$ 16 mm			
25	Lathe	Fix the straps along with a 8 mm spacer in between onto a turning fixture.				
30	Lathe	Bore $\phi$ 170	Boring tool			
35	Lathe	Bore $\phi$ 182 $\times$ 24 grooves on the straps	Boring tool			
40	Drilling	Drill and tap M16 hole	Drill bit and tap			
45	Drilling	Drill two oil holes in straps	Drills $\phi$ 6 mm and $\phi$ 3 mm			
50	-	Inspect the finished component	Boring gauge and vernier caliper			



**Q3) From the Given assemble drawing answer the following**

**a) Give the fits for the following.**

**i) Nut and Screw**

**ii) Tommy bar and Screw**

**iii) Body and Nut**

**b) Draw the following components drawings and give necessary dimensional and geometric tolerances, surface roughness values,**

**i) Body**


**ii) CUP**

**iii) Screw**


**iv) Tommy Bar**

**c) Give the process sheet for the Screw and for the tommy bar.**

From the screw jack shown in Figure. 1



3ANS)



Parts list

Part No.	Name	Matl	Qty
1	Body	CI	1
2	Nut	GM	1
3	Screw	MS	1
4	Cup	CS	1
5	Washer	MS	1
6	Screw	MS	1
7	Tommy bar	MS	1

**Process Sheet for Tommy Bar**

Part Name : Tommy Bar  
 Part Number : 4  
 Cycle Time :  
 Material : Mild Steel

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	—	Check the stock size	Vernier calipers			
10	Lathe	Clamp the work on chuck and perform facing at end	Facing tool			
15	Lathe	Turn the work to $\phi$ 20 mm	Turning tool			Tool changing needed
20	Lathe	Turn the section $\phi$ 16 $\times$ 60 mm	Turning tool			
25	Lathe	Reverse the component and perform facing at other end	Facing tool			Tool changing needed
30	Lathe	Knurling the bar	Knurling tool			Tool changing needed
35	—	Inspect the finished component	Vernier calipers, etc.			

**Process Sheet for Screw**

Part Name : Screw  
 Part Number : 2  
 Cycle Time :  
 Material : Medium Carbon Steel


Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	—	Check the size of raw stock	Vernier calipers			
10	Lathe	Clamp the work on chuck and perform facing at the end.	Facing tool			
15	Lathe	Drill centre holes and mount the work between centres	Centre drill			
20	Lathe	Turn the sections $\phi$ 36 mm, $\phi$ 60 mm and $\phi$ 25 mm	Turning tool			
25	Lathe	Produce three grooves	Parting tool			
30	Lathe	Chamfer the specified sections	Chamfering tool			
35	Lathe	Cutting square threads	Threading tool			
40	Lathe	Parting off the specified section	Parting tool			
45	Drilling	Drill cross holes of size $\phi$ 16 mm	Drill bit			
50	Furnace	Hardening the surface of work	—			
55	—	Check the finished component	Vernier calipers and other suitable measuring instruments			

Q19. Study the following...



Q4) From the assembly drawing of pipe vice as shown in below figure. Answer the following

- a) Give the fits for the following
  - i) Housing and Handle Screw
  - ii) Handle bar and Handle bar cap
- b) Draw the following components drawings and give necessary dimensional and geometrical tolerances, surface roughness values and surface treatments.
  - i) Handle Screw ii) Handle bar iii) Handle bar cap
  - iv) Movable Jaw v) set screw
- c) Give the process sheet for the Handle bar.




Part No.	Name	Raw material	Qty.
1.	Vice body	C.I - Casting	1
2.	Movable jaw	C.I - Casting	1
3.	Set-screw	MS - Std. Component	2
4.	Screw	MS - $\phi 25$ Bar stock	1
5.	Handle bar	MS - $\phi 12$ Bar stock	1
6.	Handle bar cap	MS - $\phi 16$ Bar stock	2

Fig. 11.30 (a) Pipe Vice



4ANS)



PROCESS SHEET FOR HANDLE BAR

PART NO: 5

PART NAME : HANDLE BAR

QUANTITY :1


CYCLE TIME :

MATERIAL : MILD STEEL

Sequence	Machine	Operation	Tools & Gauges	Cycle Time		Remarks
				Setup Time (min)	Operation Time(min)	
05	-	Check the length and diameter of the raw material	Vernier Calipers	-	2	
10	Lathe	Turning	Turning tool	2	3	
15	Lathe	Facing on both ends	Facing tool	2	4	
20	Lathe	External threading on both ends to a distance of 12mm	External Threading tool	2	6	
25	-	Inspection	Vernier Calipers	-	1	

**Q5). Study the given assembly drawing of the Universal Coupling as shown in below figure.**

- a) Draw the component drawings.**
- b) Apply suitable tolerances and fits.**
- c) Apply suitable geometrical tolerances to components.**
- d) Show the surface roughness symbols.**
- e) Prepare the process sheet for FORK.**



**Fig. 9.4 Universal coupling**

5ANS)




Fig. 9.5 Details of universal coupling

**Process Sheet**

Part Name : Fork

Part Number : 1


Cycle Time :

Material : Mild Steel

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the material size	Vernier calipers			
10	Lathe	Clamp the work on chuck and perform facing at end.	Facing tool			
15	Lathe	Turn the work to a size of $\phi 56 \times 38$ mm	Turning tool			Tool changing needed
20	Drilling machine	Clamp the work on drill jig and drill a hole of $\phi 30$ mm throughout	Drill bit			
25	Drilling machine	Reaming the drilled hole	Reamer			Tool changing needed
30	Drilling machine	Clamp the work on drill jig and drill a hole of $\phi 16 \times 88$ mm	Drill bit			Tool changing needed
35	Drilling machine	Reaming $\phi 16$ hole	Reamer			Tool changing needed
40	Slotting machine	Cut the key way	Slotting tool			
45	Grinding machine	Grinding the end portion i.e., $56 \times 34$ mm				
50	-	Inspect the finished component	Vernier calipers and other gauges			



- Q6). Study the given assembly drawing of the Foot step bearing as shown in below figure.**
- Draw the component drawings.**
  - Apply suitable tolerances and fits.**
  - Apply suitable geometrical tolerances to components.**
  - Show the surface roughness symbols.**
  - Prepare the process sheet for COVER.**




**Parts List**

Part No.	Qty.	Name	Matl.
1	1	Base	CI
2	1	Thrust bearing	—
3	1	Spacer	CI
4	1	Ball bearing	—
5	1	Shaft	MS
6	1	Cover	CI

**Fig. 9.8** Footstep bearing

6ANS)



Tolerances

$\phi 80$  H7 —  $80 + 0.030$

$\phi 80$  H7 —  $80 + 0.000$

$\phi 40$  m6 —  $40 + 0.025$

$\phi 40$  m6 —  $40 + 0.009$

Fig. 9.9 Details of footstep bearing

Com-



Process Sheet

Part Name : Cover

Part Number : 6

Cycle Time :


Material : Cast Iron

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the size of raw material	Vernier calipers			
10	Lathe	Clamp the component on chuck and perform step turning of $\phi 80 \times 4$ mm along with facing	Turning tool and Facing tool			
15	Lathe	Facing $\phi 120$ mm side	Facing tool			
20	Lathe	Reverse the component and perform step turning of $\phi 74 \times 5$ mm along with facing on other side.	Turning tool and Facing tool			
25	Lathe	Boring $\phi 60$ mm hole and producing serrations.	Boring tool			
30	Drilling machine	Clamp the component on drill jig and drill 6 holes of $\phi 6$ mm	Drill bit			
35		Check the size of finished component	Vernier calipers			

Q7). Draw the part drawings for the given assembly of Drill JIG and suggest the fits between mating parts.

A) Stem and Jig Plate B) Jig Plate and Bush C) Stem and Base Plate.

B) Prepare the process sheet for JIG PLATE.




**Parts List**

Part No.	Qty.	Name	Matl.
1	1	Nut	—
2	6	Bush	MCS
3	1	Jig plate	CI
4	1	Screw	MS
5	1	Stud	MS

Part No.	Qty.	Name	Matl.
6	1	Stem	MS
7	3	Screw	MS
8	1	Base	CI
9	1	Latch washer	MS

Fig. 11.12 Drill jig (Plate type)

7ANS)




www.civildatas.com

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the material size	Vernier calipers			
10	Lathe	Clamp the work on chuck and perform facing at ends of stock $\phi 28 \times 200$ mm	Facing tool			
15	Lathe	Turn the component to $\phi 25$ mm	Turning tool			Tool changing needed
20	Lathe	Parting off 6 pieces of 25 mm length from stock	Parting tool			Tool changing needed
25	Drilling machine	Drill hole of $\phi 18$ mm	Drill bit			
30	Drilling machine	Reaming the hole	Reamer			
35	-	Inspect the finished component	Vernier calipers, etc.			

**Q8). From the Assembly drawing of petrol engine connecting rod as shown in below figure. Answer the following :**


- a) Give the fits for the following
  - i)connecting rod and small end bush
  - ii) Bearing brasses and connecting rod.
- b) Draw the following component drawings and give necessary dimensional and geometric tolerances, surface roughness values and surface treatments.
  - i)connecting rod ii)Big end cap iii)Bearing brasses
  - iv)Small end bush v)Big end bolts
- c) Give the process sheet for the component bearing bush.



**Fig. 9.18** Petrol engine connecting rod



8 ANS)



+ 0.029	+ 0.039	- 0.070	+ 0.028	- 0.070
195 H6 + 0.000	$\phi$ 35 H8 + 0.000	28 g6 - 0.020	$\phi$ 22 n6 + 0.015	30 g6 - 0.020
+ 0.025	- 0.090	+ 0.021	+ 0.021	+ 0.05
$\phi$ 42 H7 + 0.000	$\phi$ 40 g6 - 0.025	$\phi$ 22 H7 + 0.000	$\phi$ 19 H7 + 0.000	$\phi$ 6 E9 + 0.02

### Process Sheet

Part Name : Bearing Bush

Part Number : 4

Cycle Time :

Material : Phosphor Bronze

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the material size	Vernier calipers			
10	Lathe	Clamp the work on chuck and perform facing at end.	Facing tool			
15	Lathe	Turn the work to $\phi 22 \times 29$ mm	Turning tool			Tool changing needed
20	Lathe	Facing at other end	Facing tool			Tool changing needed
25	Drilling machine	Clamp the work on drill jig and drill a hole $\phi 4$ mm	Drill bit			
30	Drilling machine	Drill a hole of $\phi 18$ mm	Drill bit			Tool changing needed
35	Drilling machine	Reaming drilled hole of $\phi 18$ mm to $\phi 19$ mm	Reamer			Tool changing needed
40	-	Inspect the finished component	Vernier calipers, etc.			



**Q9). From the Assembly drawing of Tail Stock answer the following**


**A) Give the fits for the following:**

- i) Barrel and spindle**
- ii) Hand Wheel and key**
- iii) Body and Barrel**

**B) Draw the following components drawings and give necessary dimensional and geometric tolerances, surface roughness values.**


- i) Body**
- ii) Spindle Bearing**
- iii) Hand Wheel**
- iv) Centre**

**C) Give the process sheet for the Barrel.**



**Fig. 9.43** Lathe tail-stock

9 ANS)



Figure

Process Sheet

Figure

Part Name : Barrel

Part Number : 2


Cycle Time :

Material : Mild Steel

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the size of component	Vernier calipers			
10	Lathe	Clamp the component on chuck and perform facing	Facing tool			
15	Lathe	Centre drilling	Centre drill bit			
20	Lathe	Mount the component between centres and turn the component to $\phi$ 35 mm and upto the complete length.	Turning tool			
25	Lathe	Clamp the component on the chuck and drill hole upto the complete length	Drill bit			
30	Lathe	Boring the inner cavity or recess.	Boring tool			
35	Lathe	Threading M16	Threading tool or tap			
40	Lathe	Reverse the component and perform facing at other end.	Facing tool			
45	Lathe	Boring the tapered hollow portion or morse taper	Boring bar			
50	Centreless grinder	Grinding the outer surface	-			
55	Milling	Slot cutting	Slitting saw type cutter			
60	Cylindrical grinder	Grinding the tapered hollow portion	-			
65		Check the size of finished component	Vernier calipers and other suitable measuring instruments			

Q10). Study the given assembly drawing of the knuckle joint as shown in below figure.


- a) Draw the component drawings.
- b) Apply suitable tolerances and fits.
- c) Apply suitable geometrical tolerances to components.
- d) Show the surface roughness symbols.
- e) Prepare the process sheet for PIN.



Part No.	Name	Material	Qty.
1.	Fork end	FS - Forging	1
2.	Eye end	FS - Forging	1
3.	Pin	MS - $\phi 40 \times 95$	1
4.	Collar	MS - $\phi 40$ Bar stock	1
5.	Taper pin	MS - Std. component	1



10 ANS)





Process Sheet

Part Name : Pin

Part Number : 3


Cycle Time :

Material : Mild Steel

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	-	Check the size of component	Vernier calipers			
10	Lathe	Clamp the component on chuck and perform facing at the end	Facing tool			
15	Lathe	Turning $\phi$ 24 mm upto a length of 80 mm	Turning tool			
20	Lathe	Reverse the component and turn $\phi$ 38 mm upto a length of 12 mm	Turning tool			
25	Lathe	Facing at other end	Facing tool			
30	Drilling machine	Clamp the component on drill jig and drill a hole	Drill bit of $\phi$ 4 mm			
35	Drilling machine	Taper reaming of hole to $\phi$ 5 mm	Reamer			
40		Check the size of finished component	Vernier calipers			

**Q11). Study the given assembly drawing of the Plummer Block as shown in below figure.**


- a) Draw the component drawings.
- b) Apply suitable tolerances and fits.
- c) Apply suitable geometrical tolerances to components.
- d) Show the surface roughness symbols.
- e) Prepare the process sheet for Cap.



Part	Part Name	Material	Qty
1.	Base	Cast iron	1
2.	Cap	Cast iron	1
3.	Bearing brasses	Bronze	1
4.	Bolt with nuts	Mild steel	1



11 ANS)



Process Sheet

Part Name : Cap

Part Number : 2


Cycle Time :

Material : Cast Iron

Sequence	Machine	Operation	Tools or Gauges	Cycle Time		Remarks
				Setup Time	Operation Time	
05	—	Check the casting size	Vernier calipers			
10	Milling	Clamp the work on milling machine and perform facing on both the upper sides of work i.e., 37 × 21 mm sections	Face milling cutter			
15	Milling	Facing on bottom sides of work i.e., 13 × 21 mm sections	Face milling cutter			
20	Milling	Facing the sides of work to 37 mm	Slab milling cutter			Tool changing needed
25	Drilling machine	Clamp the work on drill jig and drill two holes of $\phi$ 10 mm	Drill bit			
30	Drilling machine	Reaming the holes	Reamer			Tool changing needed
35	Drilling machine	Drill an oil hole of $\phi$ 4 mm at centre	Drill bit			Tool changing needed
40	Drilling machine	Counter boring the oil hole to $\phi$ 8 mm upto a length of 13 mm	Boring tool			Tool changing needed
45	Jig boring machine	Boring the R19 mm section	Single point cutting tool			
50	—	Inspect the finished component	Vernier calipers, etc			

Q12) Study the given assembly drawing of the Single Tool post as shown in below figure.

- Draw the component drawings.
- Apply suitable tolerances and fits.
- Apply suitable geometrical tolerances to components.
- Show the surface roughness symbols.
- Prepare the process sheet for Cap.




Parts list

Part No.	Name	Matl.	Qty.
1	Body	MS	1
2	Clamp screw	MCS	1
3	Wedge	CI	1
4	Ring	MS	1
5	Square block	MS	1

Fig. 19.8 Single tool post



ANS)




Parts list

No.	Name	Matl	Qty
1	Pillar	MCS	1
2	Block	MCS	1
3	Ring	MS	1
4	Wedge	MCS	1
5	Screw	TS	1

Fig. 18.14 Single tool post

**Q13) Study the given assembly drawing of the Rams bottom safety valve as shown in below figure.**

- Draw the component drawings.**
- Apply suitable tolerances and fits.**
- Apply suitable geometrical tolerances to components.**
- Show the surface roughness symbols.**
- Prepare the process sheet for Cap.**



**Fig. 19.19 Ramsbottom safety valve**

ANS)




Fig. 18.38 Ramsbottom safety valve (contd.)




Fig. 18.38 Ramsbottom safety valve